

Testing Evaluation Laboratories, Inc.

2002 Wood Court Suite 1 – Plant City, FL 33563 Phone: 813-754-9887

TEST RESULTS

Report No:

TEL 01991312

Test Dates:

April 24, 2015

Report Date:

June 26, 2015

Issued to:

Fleetwood Windows and Doors 1 Fleetwood Way Corona, CA 92879

Project Summary: Testing Evaluation Laboratories, Inc. (TEL) was contracted by Fleetwood Windows and Doors to perform tests on the 3800-T Fixed Windows at TEL's Plant City, FL test facility. *Deviation to test protocol: At request of client, we tested one structural and one impact specimen.*

Test specimen descriptions and results are reported herein.

Dade Lab Certification Number: 15-0114.08

Test Notification Number: TEL 15-004

Test Specifications:

The test specimens were evaluated in accordance with the following:

High Velocity Hurricane Zone Protocols TAS 202-94, TAS 201-94 and TAS 203-94

Test Specimen Description:

Series / Model:

3800-T Fixed Windows

Type:

Aluminum Fixed Windows

Overall Size:

181.00" x 120.00" - Specimens 1 and 1a- (OOO)

Daylight Opening:

57.00" x 117.13" - Specimens 1 and 1a - (OOO)

Glazing Detail:

See attached drawing number L-7350 for glazing details.

Frame Material:

Aluminum

Finish:

Mill Finish

For Tested Elevation, Vertical Cross Sections, Horizontal Cross Sections, Components, Frame Anchoring, Glazing Detail and Bill of Materials See Attached Drawing number L-7350.

SEQUENCE OF TESTS PERFORMED:

STRUCTURAL TESTS (TAS 202)

Specimen 1 – 181.0" x 120.0" Triple Mulled Aluminum Fixed Window (OOO)

Design Pressure	Positive 65.0	Nega	tive 65.0		
,		Pressure 1.57 PSF		SCFM/Ft^2 0.000	Result Pass
Air Infiltration (ASTM E283-04)		Pressure 6.24 PSF		SCFM/Ft^2 0.000	Result Pass
Structural Loads (ASTM	1 E330-02)				
Range	Time	Load	Location	Deflection	Allowable (Def)
	(sec)	(psf)			
Half Test Positive	30	32.50			
Design Positive	30	65.00	1	0.663"	0.667"
Half Test Negative	30	32.50			
Design Negative	30	65.00	1	0.665"	0.667"
Water Infiltration (AST	M E331-00)		Pressure 15.0 PSF	Time 15.0 M	Result in. Pass

Note #1: Water Infiltration performed after Positive and Negative half and design loads.

Structural Loads (ASTM E330-02)

Range	Time (sec)	Load (psf)	Location	Deflection	Set	Allowable (Set)
Half Proof Positive Test Positive	10 30	48.75 97.50	1	1.046"	0.005	0.480"
Half Proof Negative Test Negative	10 30	48.75 97.50	1	1.033"	0.027	" 0.480"

Deflection Locations:

Location 1 – Center of Mullion

Forced Entry Passed – No Entry

Conclusion: TEL observed no signs of failure in any area of this test specimen during the Uniform Static Load Test. In addition, specimen met the permanent set requirements. Therefore, this specimen satisfies the uniform static load test requirements of TAS 202-94.

James Hayhurst, Test Technicians

IMPACT AND CYCLING TESTS (TAS 201/203)

Specimen 1a – 181.5" x 120.0" Triple Mulled Aluminum Fixed Window – (OOO)

TAS 201 and 203 - Large Missile Impact (2 x 4 Southern Yellow Pine)

Cond. Temp	Missile	Missile	Missile	Muzzle Distance
Of Specimen	Level	Weight	Length	From Specimen
74°F	D	9.0 lbs, 0 oz.	8'-0"	17'0"

Impact Location	Results	X - Measurement	Y - Measurement	Speed
1	Pass	91.00"	60.25"	50.1 fps
2	Pass	111.00"	8.00"	50.0 fps
3	Pass	60.25"	60.00"	49.9 fps

Orientation of Missile at Impact was within +/-5° of horizontal. None of the impacts penetrated the specimens. "X" measurement is from the left edge of test specimen. "Y" measurement is from the bottom edge of test specimen.

TAS 201 and 203- Fatigue Load Cycling Design Pressure +55.0 psf / - 60.0 psf

Positive % of Test Load	Positive Pressure Range (psf)	Number Of Cycles	Average Cycle Time (Sec)
20% to 50%	11.0 to 27.5	3500	1.77
0% to 60%	0.0 to 33.0	300	1.65
50% to 80%	27.5 to 44.0	600	1.27
30% to 100%*	16.5 to 55.0	100	1.95

Negative % of Test Load	Negative Pressure Range (psf)	Number Of Cycles	Average Cycle Time (Sec)
30% to 100%*	18.0 to 60.0	50	1.80
50% to 80%	30.0 to 48.0	1050	1.38
0% to 60%	0.0 to 36.0	50	1.91
20% to 50%	12.0 to 30.0	3350	1.55

^{*}Panel deflected 4.25" from original plane at 100% Positive load and 5.50" from original plane at 100% Negative load. At the completion of cycles the door panel was operable. There were no tears in the film. In our opinion, the tape and film used to seal for air leakage did not influence the results of the test.

James Hayhurst, Test Technician

Conditions, Terms, and General Notes Regarding These Tests

The product tested <u>Has Been</u> compared to the detailed drawing, bill of materials and fabrication information supplied by the client so named herein. Our analysis, which includes dimensional and component description comparisons, indicate the tested product and engineering information supplied by the client <u>"Are Equivalent".</u> The report and representative samples will be retained for four years from the date of initial test.

These test results were obtained by employing all requirements of the designated test methods with no Deviations unless explicitly noted in test report. The test results and specimen supplied for testing are in compliance with the reference.

The test results are specific to the product tested by this laboratory and of the sample supplied by the client named herein, and they relate to no other product either manufactured by the client, a fabricator of the client or of the client or of installed field performance.

This test report does not constitute certification of this product, but only that the above test results were obtained using the designated test methods and they indicate compliance with the performance requirements (paragraphs as listed) of the above referenced specifications.

Testing Evaluation Laboratories, Inc. makes no opinions or endorsements regarding this product and its performance. This report may not be reproduced or quoted in partial form without the expressed written approval of Testing Evaluation Laboratories, Inc.

Testing Evaluation Laboratories, Inc.'s letter, reports, its name or insignia or mark are for the exclusive use of the client so named herein and any other use is strictly prohibited. The report, letters and the name of Testing Evaluation Laboratories, Inc., its seal or mark shall not be used in any circumstance to the general public or in any advertising.

Limitation of liability: Due diligence was used in performing the tests and reporting the results. By acceptance of this report, this client agrees to hold harmless and indemnify Testing Evaluation Laboratories, Inc., its employees, sub-contractors, officers and owners against all claims and demands of any kind whatsoever, which arise out of or in any manner connected with the performance of work referred to herein.

Testing Evaluation Laboratories, Inc.

Vivian K. Wright,

President

William B. Shelton, P.E. Fiorida P.E. # 26686

PF 595 TEL 01991312 Page 4 of 5

Revision Log

Rev No.	Date	Page(s)	Revision(s)	
0	0 6/26/2015 NA		Original Report Issue	

PF 595 TEL 01991312 Page 5 of 5

TABLE OF CONTENTS					
SHEET #	EET # DESCRIPTION				
1	Table of contents				
2	Test elevation				
3	Horizontal cross sections				
4	Horizontal cross sections				
5	Vertical cross sections				
6	Vertical cross sections				
7	Frame anchoring				
8	Bill of materials, components and glazing detail				

PRODUCT:		SPEC. 1, 1a		PART OR ASSEMBLY:	CHATHACO TO TICAL	BY IABLE OF CONTENTS		
							S	
							REVISIONS	
	DATE DATE							's Inc.
						Š.		TANT
	BUILDING CONSULTANTS, INC. 813.659.9197 DATE: 4/2/15 SCALE: N.T.S.							
_	DATE: 4/2/15 SCALE: N.T.S.							

₩.₩.


Ŋ 201

DWG. BY: JK LFS

CHK. BY: DRAWING NO.:

L-7350

SHEET <u>1</u> OF <u>8</u>



Testing Evaluation Laboratories Inc. Specimen Complies with Drawing
Deviations Noted - TEL#_ 01991312 Date 6/26/15 Verified by

PRODUCT:	SPEC. 1, 1a			PART OR ASSEMBLY:	SMOITW II TOLI	IESI ELEVAIIONS	
						BY	
							REVISIONS
						. DATE	
<u>ا</u>	R	a				ON	

ELEVATIONS

BUILDING CONSULTANTS, INC. 813.659.9197

4/2/15 DATE: N.T.S. SCALE:


DWG. BY:

JK LFS CHK. BY:

DRAWING NO .:

L-7350

SHEET 2 OF 8



HORIZONTAL CROSS SECTION

PRODUCT:	FLEETWOOD SPEC. 1, 1a			PART OR ASSEMBLY:	LA TIMO CIGO	TOURIZONIAL CDOSS SECTIONS	CNOSS SECTIONS
						BY	
							REVISIONS
						DATE	٠
	J ON NOW						
RW BUILDING CONSULTANTS, INC.							


813.659.9197

/2/15				
N.T.S.				
JK				

CHK. BY: LFS


DRAWING NO .:

L-7350 SHEET 3 OF 8 R.W. BUILDING CONSULTANTS INC. 2015



HORIZONTAL CROSS SECTION


PRODUCT:		SPEC. 1, 1a		PART OR ASSEMBLY:	NET ACEICOL	CDOON OFCITONS	CNOSS SECTIONS	
						BY		
						NO, DATE	REVISIONS	NTS INC.
٦	D					_		JLTAI
RW BUILDING CONSULTANTS, INC. 813.659.9197								
DATE: 4/2/15								ורםוו
SCALE: N.T.S.								ВП
DWG. BY: JK CHK. BY: LFS								
DRAWING NO.:								
		L-	-7	35	0			201
SHEET <u>4</u> OF <u>8</u>								



1	VERTICAL CROSS SECTION
5	

Testing Evaluation Laboratories Inc.
Specimen Complies with Drawing
Deviations Noted - TEL# 01991312
Date 6/26/15 Verified by

	PRODUCT:	GOOWLE FI FETWOOD	SPEC. 1, 1a		PART OR ASSEMBLY:	A OFFICE			
							B		
							VO, DATE	REVISIONS	אדש ואם.
The second secon	RW BUILDING CONSULTANTS, INC. 813.659.9197								
	DATE: 4/2/15 SCALE: N.T.S.								
	DWG. BY: JK								×. В
	CHK. BY: LFS C								
	L-7350								
	SHEET 5 OF 8								



1 VERTICAL CROSS SECTION

Testing Evaluation Laboratories Inc.
Specimen Complies with Drawing
Deviations Noted - TEL# 01991312
Date 6/26/15 Verified by

PRODUCT:	SPEC. 1, 1a	PART OR ASSEMBLY:	1 OTHOLIN	VEKTICAL CDOSS SECTIONS	CNOSS SECTIONS
				BY	
					REVISIONS
				DATE	
				NO.	

RW BUILDING CONSULTANTS, INC. 813.659.9197

DATE: 4/2/15

SCALE: N.T.S.


DWG. BY: JK

CHK. BY: LFS

DRAWING NO.:

L-7350

SHEET <u>6</u> OF <u>8</u>



FRAME ANCHORING

(2X buck installation)

Testing Evaluation Laboratories Inc.
Specimen Complies with Drawing
Deviations Noted - TEL# 01991312
Date 6/26/15 Verified by

						NO.	
[R	7	11				٦
C	ON	, / SU	V LTA	BU	ILC S,	INC	3.
				9.9			

FRAME ANCHORING

BY

PART OR ASSEMBLY:

FLEETWOOD SPEC. 1, 1a

PRODUCT:

DATE: 4	/2/15					
SCALE:	N.T.S.					
DWG. BY:	JK					
CHK. BY:	LFS					
DRAWING NO.:						
L-7350						

SHEET 7 OF 8

